

## Elevator Controller K2210 Release Notes

<b>Device Model:</b> DS-K2210	Firmware Version	ACS_DS_K22XX_ST0_GML_GM_V1.0.4_build20220216
	4200 Version	

### **Reason of Upgrade**

Add or modify functions, fix bugs, enhance products quality and meet customers' requirements.

### **Bugs Fix**

1. Fix the problem of 8 hours difference when using NTP time synchronization;

## Elevator Controller K2210 Release Notes

<b>Device Model:</b> DS-K2210	Firmware Version	ACS_DS-K22XX_GML_GM_V1.0.3_build200117
	4200 Version	

### **Bugs Fix**

1. Fix occasional device restart caused by event acquisition.;

## Elevator Controller K2210 Release Notes

<b>Device Model:</b> DS-K2210	Firmware Version	V1.0.2_build190228
	4200 Version	V2.6.5.6 build20171016

### **Bugs Fix**

1. Fix a bug that incidental uploading illegal value when upload event;
2. Fix a bug about open door timeout logic error after configure door open timeout 255s;

**Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

**Note:**

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: support@hikvision.com