

Turbo HD DVR V4.70.102 build 220215 Release Notes

(2022-02-22)

Firmware Basic Information	Firmware Version:	V4.70.102 build 220215
	SDK Version:	V6.1.4.20 build 20200320
	Onvif:	V2.2
	Player:	4.810mini
	Player library:	7.3.5.0
	Web version:	V4.0.1 build 210601
	Client version:	V2.6.13.0 build 20181115

Reason of Upgrade

• Add some new functions, modify some functions, and enhance product quality to meet customers'

requirements.

Main update

The new firmware support the EUI2.0 for M series DVR in A3 platform.

Available Modes:

K8A3	iDS-7208HUHI-M1/S
	iDS-7208HUHI-M2/S
	iDS-7216HQHI-M1/S
	iDS-7216HQHI-M2/S
K8A3FA	iDS-7216HQHI-M1/FA
	iDS-7216HQHI-M2/FA
	iDS-7208HUHI-M1/FA
	iDS-7208HUHI-M2/FA
K20A7S	iDS-7204HQHI-M1/S(C)
K20A8S	iDS-7208HQHI-M1/S(C)
	iDS-7208HQHI-M2/S(C)
	iDS-7204HUHI-M1/S(C)
	iDS-7204HUHI-M2/S(C)
K20A8FA	iDS-7204HUHI-M1/FA(C)
	iDS-7204HUHI-M2/FA(C)
	iDS-7204HQHI-M1/FA(C)
	iDS-7208HQHI-M2/FA (C)



First Choice for Security Professionals

	iDS-7208HQHI-M1/FA (C)
K20A9S	iDS-7216HQHI-M1/S(C)
	iDS-7216HQHI-M2/S(C)
	iDS-7208HUHI-M1/S (C)
	iDS-7208HUHI-M2/S (C)
	iDS-7216HUHI-M2/S(E)

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after

upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any

possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com