

PTZ Camera Firmware Version: V5.5.800

Release Note

(2021-11-26)

Firmware Version Information

For DFxxxx(T2)

IPD_H5_EN_STD_5.5.800_211009

For DYHxxx(T2)

IPTH_H5_EN_STD_5.5.800_211009

Please refer to the table below to get specific model

Camera Features

1. New Features

N/A

2. Improved Features

- Fix security issue in ISAPI

3. Leftover Issues

N/A

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.

No. 555 Qianmo Road, Binjiang District, Hangzhou
310051, China

Tel: +86-571-8807-5998

Supported Product List	
Product Category	Model Number
DFXXXX(T2)	DS-2DF8A436IXS-AEL(O-STD)(CC)(T2) DS-2DF8A836IXS-AEL(O-STD)(CC)(T2) DS-2DF8C442IXS-AELW(O-STD)(T2) DS-2DF8C842IXS-AELW(O-STD)(T2) DS-2DF8A442IXS-AEL(O-STD)(T2) DS-2DF8A442INXS-AEL(O-STD)(T2) DS-2DF8A842INXS-AEL(O-STD)(T2) DS-2DF8A442IXS-AF/SP(O-STD)(T2) DS-2DF8442IXS-AEL(O-STD)(T2) DS-2DF8442IXS-AELW(O-STD)(T2) DS-2DF6A836XS-AEL(O-STD)(T2) DS-2DF6A836XS-AELY(O-STD)(T2) DS-2DF8C825IXS-AELW(O-STD)(T2) DS-2DF8C825IXS-AEL(O-STD)(T2) DS-2DF8C842IXS-AEL(O-STD)(T2) DS-2DF8A842IXS-AEL(O-STD)(T2)



First Choice for Security Professionals

	DS-2DF8C442IXS-AEL(O-STD)(T2) DS-2DF8442I5XS-AELW(O-STD)(T2)
DYHxxx(T2)	DS-2DYH2A0IXS-D(O-STD)(T2)

Note: Models in red font are newly released models.