

Network Camera Firmware

Version: V5.5.130

Release Note

Firmware	Firmware Version:	V5.5.130 211023
Basic Information	Tilliware version.	V3.3.130_211023

Explosion-proof Camera Firmware V5.5.130 build20211023 Features

- 1. Improved Features
- Fix security issue in ISAPI

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.



Supported Product List		
Product Category	Model Number	
Explosion proof Camera	DS-2XE6825G0-(I)(L)Z(H)(S)	
Explosion proof Camera	DS-2XE6845G0-(I)(L)Z(H)(S)	
Explosion proof Camera	DS-2XE6885G0-(I)(L)Z(H)(S)	